



Industry & Facilities Division

INSPECTION CERTIFICATE N° EA07081902

BV Job Nr: IDD.TR.3655308.19.A41

PROJECT: ÇAĞDAŞ GAYRİMENKUL İNŞ. TİC.	Ref: N/A
BV Client: DUYAR POMPA VE HİDROFOR SİSTEMLERİ SAN. ve TİC. A.Ş.	P/o nr: N/A (client to BV)
Manufacturer: DUYAR POMPA VE HİDROFOR SİSTEMLERİ SAN. ve TİC. A.Ş.	P/o nr: N/A (client to Manufacturer)
Inspection requested by: DUYAR POMPA VE HİDROFOR SİSTEMLERİ SAN. ve TİC. A.Ş.	

SUPPLY / SUBJECT OF INSPECTION	ITEM / TAG Nr	QTY
Type of DSP 80 – 250 Electric Pumps	111519 211519	1 1

Scope of inspection:

Particulars: Test results found to be satisfactory according to NFPA 20 the article of 6.2.1 and the nominal values of the pumps. Test reports were approved and the suction flanges were die stamped with BV stamp.

- **Reference documents used for inspection:** NFPA 20
- **Place of inspection & date or period:** DUYAR POMPA VE HİDROFOR SİSTEMLERİ SAN. ve TİC. A.Ş. Dudullu / ISTANBUL – 07.08.2019
- **Marking and stamping:** The suction flanges were die stamped with BV stamp.
- **Annexes to this certificate:** BV Inspection Report, 7 pages.
- **Related IR No:** EA07081901

The undersigned, inspector to Bureau Veritas, certifies that the hereabove mentioned supply was inspected in conformity with the applicable requirements of the purchase order and the contractual requirements governing the mission entrusted to Bureau Veritas without any remarks.

Inspected by:

Name: Emre ACAR

Signature:

Date of issue: 07/08/2019

Inspection centre: BV İstanbul

Checked by:

Name: ALİ TAYLAN ÖZTÜRK

Signature:



Distribution: CLIENT MANUFACTURER